Nº 5484

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED $7 - 12 - 50$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	10' deef
HOUSE NO.		•
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
	NAME OF CONTRACTOR Rogers	
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.	
Brookside A	cres	22
		1 8 dech
*		13/
	10 deep	
1 1 51	0 2/4	34
SIGNED John INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE	7 m 2 7 - 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
INSPECTOR FOR CIT		
REMARKS:		

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5484 PERMI	II IO TAP	SEWER 7/12	
\mathcal{A}	assillon, Ohio,	FEE OF \$	1900
FOR WHICH PERMISSION IS GRANTED	L.	To the account of the same	
TO TAPSEWER, ON	N THE	- A	SII
Brake De achier FOPE OF	F STREET		, -
THE PREMISES BEING LOT NO.	, HOUSE NO		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.