Nº 5487

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-15-50	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	10' dec/
HOUSE NO. 802		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN		
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
30 TH ST.		4 maganisanananananananananananananananananan
		1/2/
Commission of the control of the con		W/ 25/2
	4	and the second s
A 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	and the second of the second o	And the second s
SIGNED John Chro	FILED AT ENGINEER'S O	FFICE 8 - 2 - 5 0
INSPECTOR FOR CIT	Y	
REMARKS:		

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

MASSILLON, OHIO, 19	5
Massillon, Ohio, 19	
H. Jan allendaria	
RECEIVED OF FEE OF \$.
FOR WHICH PERMISSION IS GRANTED LAND	
TO TAPSEWER, ON THE	SIDE
of 30 Th Dw AVE. TYPE OF STREET dut	
THE PREMISES BEING LOT NO. 42 192 - HOUSE NO. 802	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,	AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	

排列 的第三位的复数形式

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.