FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN DETURNED

DATE INSPECTED 8-23-50 IF SO HOW AND LOCATION FROM 184'- 72 Deep. HOUSE NO. 1720 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH WAS LATERAL AT CURB? See Sketch WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR DIANA- Laid by Remiley SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. Connected to Wye on
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH WAS LATERAL AT CURB? See Sketch WAS ATTACHED TO MAIN Yes NAME OF CONTRACTOR DIANA Laid by Remiey SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
Main Line.
72 Deep & scone. Walk on N. Side of L. Way
SIGNED R. J. Sewer between N. Curb and Walk INSPECTOR FOR CITY FILED AT ENGINEER'S OFFICE 8-28-52

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N9 11 5493 V

PERMIT TO TAP SEWER

	Ì
MASSILLON, OHIO, 195	_
RECEIVED OF CHARLES ALLOS FEE OF \$ 300	
FOR WHICH PERMISSION IS GRANTED	
TO TAPSEWER, ON THESIDE	E
of Ancien Vay E AVE. TYPE OF STREET Tomes.	•
THE PREMISES BEING LOT NO. 9126-27 , HOUSE NO. 1720	-
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND	>

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.