## Nº 5499

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

	LOCATION FROM E DOWN STREAM
HOUSE NO. 1016  DISTANCE FROM DOWN STREAM CURB LINE AND CU	
WAS LATERAL AT CURB?	. "
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	of Building Served.
3 BQ 57, 5 E	3dogs 14
and the state of t	16'doch
SIGNED John Christon INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE
REMARKS:	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## o de la compania del compania del compania de la compania del compania del compania de la compania del comp PERMIT TO TAP SEWER

	4	//
6.21	Massillon, OHIO,	FEE OF \$ 2
RECEIVED OF	John meles	
TO TAP	SEWER, ON THE	SIDE
of 3rd 16	AVE TYPE OF STREET	d
THE PREMISES BEING LOT NO.	145 HOUSE NO. 10	16

RULES OF THE DEPARTMENT OF PUBLIC SERVICE

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.