Nº 5500

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 62350	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		-
HOUSE NO. 4 5 5	DISTANCE FROM FIRST MANHOLE	.	
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		4'deep
WAS LATERAL AT CURB? Yace	ų	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Diagram	
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SE	RVED.	
1674 ST N.E	<i>y</i>	26	
many of the same o	6'4	(4)	
			de sofi
91	and the second s	0	Ø
SIGNED INSPECTOR FOR CI	FILED AT EI	NGINEER'S OFFICE	s ar 2 or Ell
INSPECTOR FOR CI			
RFMARKS:			

MANAGERIA MEDICAL MEDICAL MANAGEMENT OF THE DIRECTOR OF PUBLIC SERVICE

	Nº 5500	PE	ERMIT TO	TAP SEW	ER
			Massillon, O	оню, — 9/	/ /
	RECEIVED OF	ALLO	cna)	F	TEE OF \$2
1	FOR WHICH PERMISSION IS G	ANTED IL	a le	alken	N
	то тар	<u>- つし</u> s	EWER, ON THE	ω	sic
	of 16th).	S AVE.,	TYPE OF STREET	Alele	& Taxed

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR ALLAND

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.