Nº 5502

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Z

DATE INSPECTED 9-8-50	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	<i>K</i>
HOUSE NO. 8/3		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	7'deeh
WAS LATERAL AT CURBY	and grant the control of the second and the second	
WAS ATTACHED TO MAIN Ve 5	NAME OF CONTRACTOR ASTOM	t,
	TERAL TO WALL OF BUILDING SERVED.	
Rotch Ave	N.E.	
and the state of t	882de 6	
entre entre part de les des des la ser l'aut.	State of the state	
	7300 2/3	106
SIGNED John Ehrne	FILED AT ENGINEER'S OFFICE	10-2-50
INSPECTOR FOR	CITY Street iv. and recipies of problem in the angle of	M Mars. 445.11
REMARKS:		

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

.Gam J Vo	32 5502 V	nakom (PE	RMIT TO	TAP SEV	WER
		ng kanadag paggalah sebaggan di Alimbah di diganggalah sebagga	MASSILLON, OF	110, 9/8	. TO VIS 197 FOURT
	ECEIVED OF	Exal L	/ Drain	1	One 200 200 200 400 400 400 400 400 400 400
FOR WHI	CH PERMISSION IS G	RANTED SE	WER, ON THE	100 May 100 Ma	
OF	MITAL	77 (AVE	Destriction of Park (1995) The Control of Street	Cilles	gg a militaria de
THE PREM	HISES BEING LOT NO.	BOANGE WITH ORDIN	ANCE NO. 2323 DI	E NO. X	THE CITY COUNC

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.