

Nº 5515

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 9-29-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 903

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

41'

8' deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

OXFORD AVE. NE



32'

7' deep

6"

8' deep

41

SIGNED

John Ehrmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10-16-50

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 5515

PERMIT TO TAP SEWER

MASSILLON, OHIO.

9/29

19

RECEIVED OF

Raymond Remley

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Paul Von Gunten

TO TAP

Sanitary

SEWER, ON THE

South

OF

Elford Ave NE

AVE.,

TYPE OF STREET

near villa

THE PREMISES BEING LOT NO.

8510-8512

HOUSE NO.

903

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.