

Nº 5519

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 10-13-50IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 118DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 122' 3' deepSIZE OF PIPE USED 6"WAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN YesNAME OF CONTRACTOR Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

15th ST. N.W.
Lateral #3 used1 1220SIGNED John E. Harn

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 10-25-50

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5519

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/12 19

RECEIVED OF

J. Aston

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

Wm Lewis

TO TAP

San

SEWER, ON THE

E

OF

15th NW

AVE., TYPE OF STREET

THE PREMISES BEING LOT NO.

PA 98 122

HOUSE NO.

218

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Aston

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.