## Nº 5520

# FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

	DATE INSPECTED 10-28-50	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
	SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	9 deals
	WAS LATERAL AT CURB?	NAME OF CONTRACTOR	
	SHOW BY DIAGRAM RELATION OF LATE		6
		in a communication of the analysis of the second se	1 2 7 18 och
	<del>f</del>	The state of the s	\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \
 	SIGNED Of The Estar	202	11-10-50
	/ INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE	

#### OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

#### Nº 5520

### PERMIT TO TAP SEWER

Tan militari ke kasa alah ili kemuti dalah Silah di Majaran Jawa Baran da masa salah s	Massillon, Ohio, 19
RECEIVED OF	FEE OF SOL
	see Kline
TO TAP SEWER,	
8F 231 170 F LAVE TYPE	the trag series of the should are the
Declarde Cety Symils THE PREMISES BEING LOT NO.	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCE RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.