

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
Nº 5521 AND SIGNED WHEN RETURNED.**

DATE INSPECTED 10-21-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1112

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

79 6' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Stratford Ave



SIGNED John E. Brown

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 10-25-50

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5521

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/13 1920

RECEIVED OF A. J. Duna

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Arthur Culp

TO TAP San

SEWER, ON THE Th.

OF Stratford NE

AVE.
ST.,

TYPE OF STREET Paved

THE PREMISES BEING LOT NO. 10623-24

HOUSE NO. 1112

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Duna

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.