

5/22 ✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
Nº 5522 AND SIGNED WHEN RETURNED.**

DATE INSPECTED 11-27-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 923

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 153' 7' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Smart & Harper

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

14TH ST. S.E.



SIGNED John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 12-18-50

REMARKS: _____

NOTED BY THE CITY ENGINEER TO THE OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 5522

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/14 1920

RECEIVED OF Harper & Smart

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Hattie Shearow

TO TAP San

SEWER, ON THE W

OF 14th & E

AVE., TYPE OF STREET dirt
ST.,

THE PREMISES BEING LOT NO. 2703

, HOUSE NO. 923

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Harper & Smart

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.