

Nº 5524

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 10-24-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1224

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 122' 151' 9' deep

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lennox Ave



7' deep
6' deep
9' deep

38

30

122

SIGNED John E. Chover
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 10-25-50

REMARKS: _____

NOTED FOR THE OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

APPL N^o 5524 PERMIT TO TAP SEWER

MASSILLON, OHIO, Oct 24 1924
RECEIVED OF Raymond Remley FEE OF \$ 2
FOR WHICH PERMISSION IS GRANTED Cyril Henrich
TO TAP Sanitary SEWER, ON THE north
OF Lennox ST., TYPE OF STREET pared
THE PREMISES BEING LOT NO. 8804-8805 HOUSE NO. 1224

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Raymond Remley

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.