

9
44
✓

Nº 5529

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 10-26-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 536

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

179' 6' deep

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Kelleybrook Drive, S.E.

Lateral No. 15 used



SIGNED John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 11-20-50

REMARKS: Sewer in Harsh Ave S.E.

Meas. OK.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 5529

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/9 19

RECEIVED OF

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

24th ST SE

AVE.

TYPE OF STREET

ST.

THE PREMISES BEING LOT NO.

Pl L 324

HOUSE NO.

536

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Dean

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.