FOLLOWING DATA TO BE ANSWERED BY INSPECTOR \mathbb{Z}_{ℓ} AND SIGNED WHEN RETURNED.

DATE INSPECTED 10-26-50 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 1222	
SIZE OF PIPE USED DOWN STREAM TO DITCH AT 65 8 dec 6	
WAS LATERAL AT CURBY Yet C	
WAS ATTACHED TO MAIN Ves NAME OF CONTRACTOR Keuher	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	4
ang militar di kanalang membang bili melangkan bilang membang mengang mengang bili salah di kanalang mengang b Sampang bilang digipanggan panggang di kanalang mengang mengang mengang penggang mengang mengang bili salah di	The s
and the control of th	1
1 65 1/2	1000
SIGNED John Ehmer FILED AT ENGINEER'S OFFICE 11-20-5)
INSPECTOR FOR CITY A CONTROL OF THE	

Nº 5531 PERMIT TO TAP SEWER

MASSILLON, OHIO, 15 RECEIVED OF PEE OF \$ 2 FOR WHICH PERMISSION IS GRANTED TO TAP SEWER, ON THE LAST OF AVE., TYPE OF STREET THE PREMISES BEING LOT NO. 10719, HOUSE NO. 1222

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR C. Kluyen

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.