FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

1-3-51			1
DATE INSPECTED	. IF SO HOW AND LOCATION FR FIRST MANHOLE DOWN STREA		
HOUSE NO. 1204	THE MANUEL CONTROLL	:	
and the second s	DISTANCE FROM FIRST MANH	OLE * 1 FOR STATE /	1
SIZE OF PIPE USED 6	PROWN STREAM TO DITCH AT	51	7' Deep
WAS LATERAL AT CURRY YES	CURB LINE AND DEPTH	Constitution of the consti	
WAS LATERAL AT CURBY / C.S	•		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Keuper	-
SHOW BY DIAGRAM RELATION OF LATE	THE STATE OF THE S		
SHOW BY DIAGRAM RELATION OF LATE	TO WALL OF BUILDING	S SERVED.	
N			the second second
San Carlotte San Carlotte		7'Deepo	
o a carabbe a la la tara de la caracega a lamby de 1890 e 1880 e 1890 e la caracida de la caraci	na a viva da na anta a su su su su su su su a su su su su su de	7151	
		2	
orkus node veto va septimbre vice ovideli test.		A 44 B	A 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	7'Drep-	App. E.	Curb Lines
m		3/22	
		Alere are confer as all	1 A Carrie
			TET JETTINI
SIGNED K.J.		<u> </u>	7
INSPECTOR FOR CI	ITY	T ENGINEER'S OFFICE	10000
toord of friedlightsplantage.	Partition if at tooldine	d gaibhad le siliw 🔻 🕒	
REMARKS.	and the second s		

Nº 5534 PERMIT TO TAP SEWER

	in a secretary parameters of the parties of the control of the con
٠.	MASSILLON, OHIO,
	the state of the s
	RECEIVED OF FEE OF \$00
	The state of the s
	FOR WHICH PERMISSION IS GRANTED
	TO TAP SEWER, ON THE
	OF AVE., TYPE OF STREET
	THE PREMISES BEING LOT NO. 122 HOUSE NO. 1304
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI
	RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
	NAME OF CONTRACTOR 1 616 ACT

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.