FOLLOWING DATA TO BE ANSWERED BY INSPECTOR $\sqrt{2}$ AND SIGNED WHEN RETURNED.

DATE INSPECTED 1-20-56	IF SO HOW AND LOCATION FROM: FIRST MANHOLE DOWN STREAM
HOUSE NO. 124	
	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	CURB LINE AND DEPTH 123
WAS LATERAL AT CURB?	<u>Description of the second of </u>
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Remley
	ATERAL TO WALL OF BUILDING SERVED.
Tremont	
and the second of the second o	
	AND
4.46 - 18.	10'40
SIGNED OFFI	FILED AT ENGINEER'S OFFICE Tapped. 12
INSPECTOR FO	R CITY. Properties of the second section of the sectio
DEMARKS AND	na dika nasarah mendilan mendilan danggarakan pasang dimbabahkan bermilah hakarah 1900 di dibermilan dibermila Bermilan dibermilan dikan mendilan pada pengan pengan bermilan dibermilan bermilan dibermilan dibermilan diber

new line for OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
NO 12 55 400 12 12 12 12 12 12 12 12 12 12 12 12 12
Nº 5540 PERMIT TO TAP SEWER
Ellar drainage
MASSILLON, OHIO,
RECEIVED OF Carpmend Rember FEE OF \$ 2"
FOR WHICH PERMISSION IS GRANTED MATCHERY LANCEN
TO TAP Danitary SEWER, ON THE MOSTLE
of rement and Mave Type of STREET pare it
THE PREMISES BEING LOT NO. 314 HOUSE NO. 124
Work to be done in accordance with Ordinance No. 2323, duly passed by the City Counci Rules of the Department of Public Service.
NAME OF CONTRACTOR Raymond Remed

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.