

Nº 5544

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-15-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 2836

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 54' 9' deep



WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lincoln Way N.W.



SIGNED _____

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 1-24-51

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5544

PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/18 1918

RECEIVED OF

R. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Alfred Greaser

TO TAP

San

SEWER, ON THE

N.

OF

General Waymout

AVE.,

TYPE OF STREET

Paved

THE PREMISES BEING LOT NO.

179

HOUSE NO.

2836

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note: This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.