

Nº 5550

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-13-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 811

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 58' 8' 6" deep

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED

30TH ST. N.W.

N. →

6' deep

6

60

20

8' 6" deep

58

SIGNED John E. Egan

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 1-24-51

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 5550

PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/18 19

RECEIVED OF

R. Remley

FEE OF \$ 2⁰⁰

FOR WHICH PERMISSION IS GRANTED

Thebens

TO TAP

San

SEWER, ON THE

W

OF

30th NW

AVE., TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

Plat 192

HOUSE NO.

811

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.