

Nº 5551

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 11-14-56

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 654

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 75' 9' deep

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Bemley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Noble Pl. N.W.

N

0

75'

9

80

5

7' deep

9' deep

SIGNED

John Elsworth

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

1-24-51

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
N^o 5551 PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/18 19

RECEIVED OF

R. Remley

FEE OF \$ 3⁰⁰

FOR WHICH PERMISSION IS GRANTED

Henry Lindsay

TO TAP

San

SEWER, ON THE

OF

Noble Pl

AVE.
ST.

TYPE OF STREET

dent

THE PREMISES BEING LOT NO.

of L 218

HOUSE NO.

656

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.