FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-2-50	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 221(
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	9 Deep
WAS LATERAL AT CURBY YES	The state of the s	•
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR REMIEY	<u> </u>
SHOW BY DIAGRAM RELATION OF LATE		
o in the complete fraction was a first of the complete of the		
L. B. O. William Brown C. C.	The state of the s	•
n erito e recente e no orienzabarana antara e 1120 de está. Tenente en esta en esta en esta en esta en entre en esta en entre en entre en entre en entre en entre en entre	Lq Deep	N .
•		13
	9'Deep / Will A Days	. = ch.l.
<u>^</u>	Appre	x. s. curb Li Main Sewer
SIGNED R F. Smyder		- Mamseur
INSPECTOR FOR CI	TY (and in region of confidence for this lay that	2 - 6 6 57
REMARKS:	en elektrone elektronia orta ortakisteksi (h. 1945). 	

Nº 5565 PERMIT TO TAP SEWER

	The second of th
•	MASSILLON, OHIO, 15
L	FOR WHICH PERMISSION IS GRANTED
	TO TAP SEWER, ON THE
•	OF ANE. TYPE OF STREET DELL
	THE PREMISES BEING LOT NO. 6009- 6020, HOUSE NO. 22//
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI
1	RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
	NAME OF CONTRACTOR PROPERTY OF COLUMN AND CO

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.