## Nº 5570 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 10-2:	1F SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO.		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  U DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	3 doc/
WAS LATERAL AT CURB? Y		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Remiey	Const.
SHOW BY DIAGRAM RELATION	OF LATERAL TO WALL OF BUILDING SERVED.	
reserv	oir Dr. NE	156'deep
	and the second of the second s	Sand deep
e i Karanti, marina mata aya mata ist	in the second of the protection of the second results are also read to the second results.	m 100 / 4
	3424	
	The state of the s	18 39
·		The state of the s
SIGNED Other C	FILED AT ENGINEER'S OF	FICE 2 = (
/ INSPECT	OR FOR CITY	•
REMARKS:		

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 19

RECEIVED OF REMISSION IS GRANTED SEWER, ON THE

OF REMISSION OF STREET AND SEWER OF STREET ST., TYPE OF STREET

THE PREMISES BEING LOT NO. 196 Wales Kal

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL

Nº 5570

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.