

Nº 5571

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 2-2-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2971

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

2.5

WAS LATERAL AT CURB?


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Bentley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lincoln Way N.W.



25

SIGNED

John H. Humer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

2-26-51

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
Nº 5571 PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/30 19

RECEIVED OF

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE.,

ST.,

TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.