

Nº 5572

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 11-17-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 6' - 7' deep

HOUSE NO. 3051

SIZE OF PIPE USED 6

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 6' 7' deep


WAS LATERAL AT CURB? -

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Bennley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lincoln Way, W.



SIGNED John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 2-6-51

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 5572

PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/30 19

RECEIVED OF

FEE OF \$ 3.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE. TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.