## Nº 5574 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

HOUSE NO. 3 347	1F SO HOW AND LOCATION FROM 56 To MH @ VINCY 2
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE TO ACCUSE AND ACCUSE AND ACCUSE AND ACCUSE LINE AND DEPTH
WAS LATERAL AT CURB? No	2. 2. 2. 2. 3. 3. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4.
WAS ATTACHED TO MAIN 45	NAME OF CONTRACTOR REPORT / CYT
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
27 22 57	NW.
<b>A</b>	
and the company of the control of th	Live to the countries of the environmental and the environmental a
	0756
SIGNED John Bonn	FILED AT ENGINEER'S OFFICE 2-6-5/
REMARKS: Dutside Grbi	Limits walder in an inviting in the

## THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF PUBLIC SERVICE

,	Nº 5574 PERMIT TO TAP SEWER
	Massillon, Ohio,
	RECEIVED OF 1. Canal 1 FEE OF \$2)
	FOR WHICH PERMISSION IS GRANTED
	TO TAP LAND SEWER, ON THE
: .	OF 2716 DE AVE. TYPE OF STREET 21/7
	THE PREMISES BEING LOT NO. W 7 7 330 HOUSE NO. 34755
·	Work to be done in accordance with Ordinance No. 2323, duly passed by the City Counc
	RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
	NAME OF CONTRACTOR Republic
	and the Artist and the control of th

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.