

Nº 5579

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED.

DATE INSPECTED 1-12-51

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_

HOUSE NO. 101

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_



WAS LATERAL AT CURB? \_\_\_\_\_

WAS ATTACHED TO MAIN \_\_\_\_\_

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

1<sup>ST</sup> ST N.W.



SIGNED John E. Brown

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 2-26-51

REMARKS: Tapped in Storm sewer, in Rear.

# OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5579

## PERMIT TO TAP SEWER

MASSILLON, OHIO, 2/9 1920

RECEIVED OF A. J. Deana

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Joe Lopez

TO TAP Law

SEWER, ON THE W

OF 1st NW

AVE., TYPE OF STREET Paved

THE PREMISES BEING LOT NO. 9176

HOUSE NO. 101

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Deana

**Note.** This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.