

Repair of Existing lines only.

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

Nº 5582

DATE INSPECTED 2-20-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 204

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

This house faces Tremont St.
but the sewer comes
out the back and runs
to Charles St. Sewer.



Garage &

Conc. Drive

SIGNED

R. J. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Existing 4" sewer dug up and relaid from
at edge of driveway to house.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
Nº 5582 PERMIT TO TAP SEWER

MASSILLON, OHIO, 2/31 1924

RECEIVED OF D. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Wm. Remley

TO TAP San

SEWER, ON THE N

OF Remley St

AVE.,

TYPE OF STREET Paved

ST.

THE PREMISES BEING LOT NO. 1145

HOUSE NO. 204

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.