## 5604

### FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

HOUSE NO. 1629  SIZE OF PIPE USED 6"  WAS LATERAL AT CURB? YES  WAS ATTACHED TO MAIN	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH  NAME OF CONTRACTOR  DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT  JIANA
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
	Marie Land Company of the Marie Company of the Comp
akuren egi energizia eta eta eta eta eta eta eta eta eta et	Second and and the CiDeep
	7' Deep 15 W. Curb
SIGNED Of Inishime	Manual Connection
INSPECTOR FOR C	

#### HELD THE CALL THE RESIDENCE OF THE DIRECTOR OF PUBLIC SERVICE

# Nº 5604

## PERMIT TO TAP SEWER

MASSILLON, OHIO,	5/7/51
RECEIVED OF 1. 1 ara	FEE OF S
FOR WHICH PERMISSION IS GRANTED Carl Street	La partir de la partir
- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	
TO TAP Danitary SEWER, ON THE	wet
OF CIVIL TON MENE TYPE OF STREET	dut
THE PREMISES BEING LOT NO. 7332, HOUSE NO	1629

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.