Nº 5607

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR $^{24-7}$ AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-14-51	IF SO HOW AND LOCATION FROM	6 É Deep
HOUSE NO		· ·
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURBY NO.	and the state of t	; ;
WAS ATTACHED TO MAIN SEE Sketch	NAME OF CONTRACTOR HAND	
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	. N
Connected at main)	on"Y"	
af main)	Int. Dep	
and the many of the live & the parameters and	The state of the s	1. Side Walk
· · · · ·	4 115	Main Sewer beti
SIGNED F. Smyder	6/2 Deep	Curb & Walk.
INSPECTOR FOR CIT	rollissali of bolding al ballifad le silav	
REMARKS:		•

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER ASSILLON, OHIO. PEE OF \$2 FOR WHICH PERMISSION IS GRANTED TO TAP AVE. THE SEWER. AVE. THE SEWER.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI. RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR FOR) Chon

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.