Kelay Job

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-18-51 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 957	
SIZE OF PIPE USED DISTANCE FROM FIRST MANHOLE CURB LINE AND DEPTH	18 L' Deep
WAS LATERAL AT CURBI	ora fasova o visioni
WAS ATTACHED TO MAIN NAME OF CONTRACTOR	Hann
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED	.
	December 1
The state of the s	5. Curb
11/26 Dec	P ✓ WA
0 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Main Sewer
SIGNED R-J. Smyder FILED AT ENGINE	ERIS OFFICE 57-23-57
REMARKS:	

	OFFICE OF THE D		e - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
Nº 15613% 414	PERMIT	TO TAP	SEWER
iji. British samaran Balilin samaran J <u>alah</u> Samaran	n den en e	IILLON, OHIO,	5/17/51
RECEIVED OF	d Dran	n	FEE OF \$
OR WHICH PERMISSION IS GRANTED	. W. 91	Lint	
O TAP Sandany	SEWER, ON TH	/	South
Iremont o	AVE. TYPE OF ST	rreet	ared
HE PREMISES BEING LOT NO. 3/2		. HOUSE NO.	957

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.