## No. 5619 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-24-	IF SO HOW AND LOCATION FROM FIRST MANHOLE DESCRIPTION STREAM	10 dech
HOUSE NO. 633	The state of the s	7.
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	8'doch
WAS LATERAL AT CURB7	<ul> <li>Best Description of the resonance of the contract of the contract</li></ul>	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Hann	
	ATERAL TO WALL OF BUILDING SERVED.	
231d 57. E	X	
lining of the community of the second of T		
	The same of the same and the same of the s	
The Marie & Little	The rest of the second of the	8'deeli
0 1 51	<u>e</u> 1.29;	101-1 -
SIGNED 11222 CAT	FILED AT ENGINEER'S OFFICE	6-18-51
INSPECTOR FO	echi politice. V. as recides si paiblica it silem Ti	

## THE SHADOW AND THE PROPERTY OF A STORY OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 5619 PERMIT TO TAP SEWER

and the second of the second o
MASSILLON, OHIO,
RECEIVED OF The Continue FEE OF \$ 2
FOR WHICH PERMISSION IS GRANTED
TO TAPSEWER, ON THE
OF 330 nw AVE TYPE OF STREET dut
THE PREMISES BEING LOT NO. 11988 Outcelle, House No. 633
Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR Hann.

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.