FOLLOWING DATA TO BE ANSWERED BY INSPECTOR N° 5632 AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-16-51	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 15/9		
and the second of the control of the second	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	8' dech
WAS LATERAL AT CURB?	 In the particular control of the contr	•
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	arley.
SHOW BY DIAGRAM RELATION OF LATER	1, 1	
14 th ST SE,	258	
		★
BERTHARD BANK AN AMARIKA BANKA BANKA AMARA A	ter en la gradient de la servició de la contraction de la contraction de la contraction de la contraction de l La contraction de la	
SIGNED I Am Element	12' FILED AT ENGINEER'S OFFICE	× 3 4 e. 4
REMARKS: SEWEF CH PE	artististist me mitinding ding	14705 110

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

ing the state of t	Water
MASSILLON, O	HIO,
RECEIVED OF Milbert Carl	FEE OF \$2
	1/ 1/2 10/10 March
FOR WHICH PERMISSION IS GRANTED	on just
TO TAR Sandan	1.41
OF 14 M 1 E AVE. TYPE OF STREET	dut
5330	se No. 1519
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, D	ULY PASSED BY THE CITY COUNCI

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Selbert Carley

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.