

15
10
✓

Nº 5645

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-28-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 959

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

29' 8' Deep

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN


NAME OF CONTRACTOR

Hann

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

→ N

Return to Don



SIGNED R. F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 8-6-51

REMARKS: Lateral in rock from main to
Walk Line.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5645

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/21 1915RECEIVED OF Fred HannFEE OF \$ FOR WHICH PERMISSION IS GRANTED Robert EaganTO TAP sanitarySEWER, ON THE southOF Cherry Rd N.W.

AVE.,

TYPE OF STREET dirt

ST.,

THE PREMISES BEING LOT NO. Q.2

193

HOUSE NO. 959

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Fred Hann

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.