

Nº 5650

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-29-51

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

HOUSE NO. 806

SIZE OF PIPE USED 6

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

70'

5' Deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Hann

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

R. F. Smyth  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

# OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5650

## PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/29 1918

RECEIVED OF Frank Shuman FEE OF \$ 3.00

FOR WHICH PERMISSION IS GRANTED Frank Shuman

TO TAP Frank Shuman SEWER, ON THE 107

OF Frank Shuman AVE., TYPE OF STREET Frank Shuman  
ST.,

THE PREMISES BEING LOT NO. 8526, HOUSE NO. 806

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Frank Shuman

**Note.** This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.