Nº 5662

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-20-51	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 943		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	3. 6" Jech
WAS LATERAL AT CURB?	and the control of the state of	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Diana	
SHOW BY DIAGRAM RELATION OF LATER	The state of the s	
9 TH 5 T,	N, E	6
	on de la companya del companya de la companya del companya de la	7.6.4
ina benedita ing presidencia na pangabana at mililang at menganggabana at menganggaban at menganggaban at meng Panganggaban panganggaban panganggaban panganggaban at menganggaban panganggaban panganggaban panganggaban pan		17
	109	21)
1. 1. 5. 1.	0	1
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE_	8-18-51
REMARKS:	a deset physician i priblicate disco-	- · · ·

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5662 PERMIT TO TAP SEWER

Massillon, Ohio,
RECEIVED OF A Deans FEE OF 5
FOR WHICH PERMISSION IS GRANTED LEVEL Sharl
TO TAP SEWER, ON THE
OF AVE TYPE OF STREET
THE PREMISES BEING LOT NO. 752 (- 29 , House No. 943
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCI RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR / Jana

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.