$N_{ m o}$	:	5	67	7	

DATE INSPECTED	·
HOUSE NO. 753	
SIZE OF PIPE USED DISTANCE, FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 550	5 dech
WAS LATERAL AT CURB? 1-05	,
WAS ATTACHED TO MAIN Yes NAME OF CONTRACTOR Dialza	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
Warren Ave. S.W.	5
Company of the Compan	5:2
race and recover the mean common at the left of the manifestation of the consequence and second or an entire of	3
- 1 350	sided 5
the state of the s	
	The second secon
SIGNED FILED AT ENGINEER'S OFFICE	7- 2. St or 5-1
PEMARKS	

## Nº 5677

## PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/25/5/
RECEIVED OF WILL AND SEE OF SZ
FOR WHICH PERMISSION IS GRANTED Lorge Curchia
TO TAP! Sandary SEWER, ON THE West
of Margen and MAVE., TYPE OF STREET dirt
THE PREMISES BEING LOT NO. 47/1 HOUSE NO. 733

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Counce Rules of the Department of Public Service.

NAME OF CONTRACTOR 4 11 ana

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.