

Nº 5688

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 2603

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

39' 7' deep



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED

Harsh Ave. S.E.



SIGNED John Chmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 9/24/51

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5688

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/17 1902

RECEIVED OF A. J. Deane

FEE OF \$ 1.00

FOR WHICH PERMISSION IS GRANTED to tap

TO TAP main

SEWER, ON THE main

OF Fourth & E

AVE.,
ST.,

TYPE OF STREET Block

THE PREMISES BEING LOT NO. 4316

HOUSE NO. 2123

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR L. J. Deane

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.