

Nº 5696

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 9-11-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

32'

10 deep

HOUSE NO. _____

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

23RD ST, N. W. EXT.

← N →



SIGNED

John E. Egan
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9/24/51

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
Nº. 5696 PERMIT TO TAP SEWER

9/17
MASSILLON, OHIO, 1915

RECEIVED OF A. J. Deane

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Water Main

TO TAP San

SEWER, ON THE

OF 23rd W. W. St.

AVE., TYPE OF STREET Dist.

THE PREMISES BEING LOT NO. _____

HOUSE NO. _____

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Deane

Note. This permit covers work outside of building only. Any work i
walls of building is subject to Massillon Board of Health Regulations.