Nº 5701

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 9-29-5/	if so how and location from 90	8. Lech
HOUSE NO.		· · · · · · · · · · · · · · · · · · ·
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	une. Il 1912 il divini il massioni atalici il consistenti di saraken il cali di L	·
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR ROSETS	
SHOW BY DIAGRAM RELATION OF LATE		
Singing Brook	Pr.	
and the second control of the second control	78.66	
i i		
A HOLL OF THE THE RESIDENCE THE PROPERTY OF TH	A take to dynamic or however an extract and where the contract of the contract and the contract of the contrac	
	1 W Management of the	8 dech
1 6 50	La contraction of the contractio	
SIGNED your Chare	FILED AT ENGINEER'S OFFICE	0/6/51
INSPECTOR FOR C	ny. E nestien ivi en relitien ei terlichtet bezitete	

## COFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 22 5701 PERMIT TO TAP SEWER

:	The second of th
	MASSILLON, OHIO,
* 	RECEIVED OF THE PROPERTY OF SEE OF \$ 5
	The state of the s
FC	DR WHICH PERMISSION IS GRANTED
тс	TAP SEWER, ON THE
O,	Ung Br Du AVE. TYPE OF STREET dut
ΤΕ	IE PREMISES BEING LOT NO

Work to be done in accordance with Ordinance No. 2323, duly passed by the

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.