

Nº 5712

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 8-4-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 904

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 92' 4'


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Rentley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Tremont Ave S.W.



TREMONT AVE

Gas
Station

12

3' deep

8
2

92

4' deep

12

SIGNED

John Channer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10/31/51

REMARKS:

Sewer in 9th St. S.W.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
Nº 5712 PERMIT TO TAP SEWER

MASSILLON, OHIO, Oct 25 19

RECEIVED OF Raymond Remley FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED V. H. Meyer

TO TAP Sanitary Sewer SEWER, ON THE North

OF Remont St AVE., TYPE OF STREET Paved

THE PREMISES BEING LOT NO. 1810, HOUSE NO. 904

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Raymond Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.