Nº 5718

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-3-51	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 953	THE HANGOLE BOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 26 Tahhed	4 deaps
WAS LATERAL AT CURB7	to the second section of the members of after them.	•
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Remiey	
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	141804
9 th st.	NEW CONTRACTOR OF THE PROPERTY	
If the first operation of the first section $(0,1)^{2}$, $(0,1)^{2}$	and the second of the second o	70 M
egypti egypt alember eller ett i sak skemtig ett. S		17 4 deep
en e	925 57.	27
and the		
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE	10/31/51
REMARKS:		

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE Nº 5718 PERMIT TO TAP SEWER

 MASSILLON, OHIO, 10-25 19
 RECEIVED OF FEE OF S 3 H
 FOR WHICH PERMISSION IS GRANTED AND AND AND AND AND AND AND AND AND AN
 TO TAP SEWER, ON THE West
 OF 97 ME AVE. TYPE OF STREET
THE PREMISES BEING LOT NO. 7533 , HOUSE NO. 953
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
NAME OF CONTRACTOR ROLL SERVICE.
0

Note. This permit covers work outside of building only. Any work in

walls of building is subject to Massillon Board of Health Regulations.