FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-16-51	IF SO HOW AND LOCATION FROM Y 97 Stg.
HOUSE NO. 991	
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 72 DCCP.
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR KEYNLEY
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
and the Company of the Market State of the Company of the State of the	2.13
	Porch
en er en	and the second form of the company o
	7= Deep > /14'
	Main Sewer Line.
SIGNED R. F. Ample	FILED AT ENGINEER'S OFFICE 10129/51
	e nedsteenistees doefdwari gallilling koediew
REMARKS:	

OFFICEROF THE DIRECTOR OF PUBLIC SERVICE

N_{\cdot}^{0} 5723

PERMIT TO TAP SEWER

1900年(1907年) - 1907年(1907年) - 1907年 - 1	
Massillon, OH	10, 10-25 19
\mathcal{L}	en de la companya de La companya de la co
RECEIVED OF Krunned Kendly	FEF OF S 2
A Company of the Comp	The second of th
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5. E. Ebbert
FOR WHICH PERMISSION IS GRANTED	
	and the second s
TO TAP Double Sewer, ON THE	which is the state of the state
OF CROWN QUAVE TYPE OF STREET	
ST. ,	
9736	991
THE PREMISES BEING LOT NO. HOUSE	E NO.
	,

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council Rules of the Department of Public Service.

NAME OF CONTRACTOR Removed Remoley

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.