

~~Return To Ditch~~

12
79

Nº 5730

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 11-12-51

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 280 - 9' deep

HOUSE NO. 263

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH

WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN


NAME OF CONTRACTOR Keuber

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Hayes Ave N.E.



7' deep



9' deep
280

SIGNED John E. Humer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 11-27-51

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 15730

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/3 1922

RECEIVED OF

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.