

~~Return To District~~

11-15

Nº 5739

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 10-12-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1421

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 219' 8 deep



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Keuper

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Keuper Ave N.E.



219

SIGNED John E. Brown
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 11-27-51

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº. 5739

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/2 1921

RECEIVED OF C. Kasper FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Same

TO TAP San SEWER, ON THE W

OF Kasper Dr AVE., TYPE OF STREET Dist
ST.

THE PREMISES BEING LOT NO. Out 10921 HOUSE NO. 1521

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Kasper

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.