Nº 5750

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 1-2/-52 IF SO HOW AND LOCATION FROM	
FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2557	
SIZE OF PIPE USED	6'dech
WAS LATERAL AT CURB? Yec	•
$oldsymbol{\iota}$	
WAS ATTACHED TO MAIN V-S NAME OF CONTRACTOR DIANA	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
and the state of t	
Harsh Ave, S.E.	172
	11/24
$\frac{5}{2}$	
the manufacture of the second	72.36
$m{m{arphi}}_{i}$. The first property of $m{ar{J}}_{i}$ and the first property $m{ar{J}}_{i}$	•
	•
1 64. 6.10.	N .
A 4/ 57/ 1-10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	and the same of th
SIGNED for Latine FILED AT ENGINEER'S OFFICE	2/19/52
INSPECTOR FOR CITY	
DEMARKS.	*

Nº 5750

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

er en	Massillon, Ohio, 1/19/52 19
RECEIVED OF	/ rana FEE OF \$ 2"
FOR WHICH PERMISSION IS GRANTED	7. Smith
TO TAP Sanctary s	EWER, ON THE Siruth
OF Javes	TYPE OF STREET
THE PREMISES BEING LOT NO.	3/6 HOUSE NO. 2559

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR / / / an a

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.