FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 751 AND SIGNED WHEN RETURNED.

	DATE INSPECTED 1-21-52 IF SO HOW AND LOCATION FROM TApped 100'
•	HOUSE NO. 447 17 17 17 18
	SIZE OF PIPE USED DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH NO 5 TREET DEPT
	WAS LATERAL AT CURB?
	WAS ATTACHED TO MAIN 185 NAME OF CONTRACTOR HAND
	SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
	N fi Sippo BIVA. 9. 19-6" Deep
	SIGNED RT SIGNED FILED AT ENGINEER'S OFFICE 1-28-52
	REMARKS: House faces 17 thst. No lateral here so sewer
	was tapped in Sinna Blod on Sinna Truck

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE 5751 PERMIT TO TAP SEWER 10481-10482 WITH ORDINANCE No. 2323, DULY FASSED BY THE CITY COUNCIL $au_{ m Rules}$ of the Department of Public Service.

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.