5755 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 3-4-52	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 1625			•
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	226.	62 dech
WAS LATERAL AT CURBI Yes	★2. 「おります」、またみを作り、一個	on one en en tiego en tertença optigate	•
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Diana	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
10 th ST. N.	The second secon	2 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	10
en e	ing sa Pangalang ang Pangalang at Sangalang at Sangalang at Sangalang at Sangalang at Sangalang at Sangalang a Sangalang at Sangalang at Sangal	e make kalenda kanan ang a	1 1
h.f.	· · · · · · · · · · · · · · · · · · ·	•	
en e		weeks to the second way?	150
·	ti da karanta karanta Karanta karanta karant	and the same of feet	
		226	/14
			سسير جمعين استعادات
1 1. 54			
SIGNED INSPECTOR FOR CITY	FILED AT E	NGINEER'S OFFICE	10/52
一个一个人的现在分词 化二甲基甲基磺胺	callinoù at soajdar e i	anionari bi elimo	•
REMARKS:			

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL

 N_{\bullet}^{0} 5755

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.