

Nº 5764

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. Rear 1125

SIZE OF PIPE USED 4" G.I.P.

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Whisler, Plumber

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

14TH ST., S. E.

N



SIGNED John E. Hurst
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 4/10/52

REMARKS: Connected from house in front, iron pipe

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 5764 PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/20/52 1952
RECEIVED OF Edward Bray FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED Edward Bray
TO TAP Sanitary SEWER, ON THE West
OF 14th St AVE., TYPE OF STREET Land surface
THE PREMISES BEING LOT NO. 2269 HOUSE NO. Rear 1125

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.