Nº 5767

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

HOUSE NO. 1928 SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	7. I ref
WAS LATERAL AT CURBI	. 1994 - Malfall Carlos de Artes de la composition de la composition de la composition de la composition de la Composition de la composition de la co	•
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR DIGITOR	
SHOW BY DIAGRAM RELATION OF LATER		
Vermont Ave	N.E.	7
$p_{\boldsymbol{\theta}}(\boldsymbol{\theta}_{i},\boldsymbol$	nder 🗷 er et sammels met lætte næt å møjar 🔻	150
	244, 76	2/5/
SIGNED John Stanting INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE	3/29/52
REMARKS:	la colling del car limble e si girilidadi in elievo	

Nº 5767

PERMIT TO TAP SEWER

Massillon, Ohio, 777 at 74 19
RECEIVED OF Land
FOR WHICH PERMISSION IS GRANTED JOHN & STAR LICK
TO TAP SCINITION SEWER, ON THE MOUTH
OF AVE., TYPE OF STREET CHAPTER
THE PREMISES BEING LOT NO. 6158, HOUSE NO. 1926
Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council Rules of the Department of Public Service.
NAME OF CONTRACTOR X Dianol

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.