FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED $\frac{y-1-52}{2}$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	32.	16 deap
HOUSE NO. 7 3 2		•	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURET		en form of the agencies	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Diana	
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SE	RVED.	
30 74 57			6
	<u> </u>		
	The state of the s	randing exact to	
		10 1 oca	
		· pp - + 🔊 - 4 1 P	
SIGNED John Ehr			9/10/
INSPECTOR FOR CIT	Y Though of the sine at the	IGINEER'S OFFICE	/////
REMARKS:	in the control of the	10 4 4 4 7 1 1 4 2 1 4 2 1 4 4 4 4 4 4 4 4 4 4 4 4	1

Nº 5773

NAME OF CONTRACTOR

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Massillon, Ohio, Wail 10	9
RECEIVED OF a gubind FEE OF \$ 2.	C
and the control of t	
FOR WHICH PERMISSION IS GRANTED	
FOR WHICH PERMISSION IS GRANTED	1
	7.
TO TAP SEWER, ON THE	
of 30 99 W AVE. TYPE OF STREET CLUT	<u>. </u>
THE PREMISES BEING LOT NO. 10903 , HOUSE NO. 832	
Waste and the manufacture of the second seco	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNC	21:
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	
and the contract of the contra	

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.