

Nº 5798

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-8-52

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

HOUSE NO. 519

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

SIZE OF PIPE USED 6

113'

6' deep



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

27th St SE



SIGNED

John E. Humer  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

5/10/52

REMARKS:

Nº 5798

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO

5-7

19

RECEIVED OF

*Rendley*

FEE OF \$

2.1

FOR WHICH PERMISSION IS GRANTED

*C P Crowl*

TO TAP

*Sanitary*

SEWER, ON THE

*sewer*

OF

*27th St*

AVE.  
ST.

TYPE OF STREET

*dirt*

THE PREMISES BEING LOT NO.

*6913*

HOUSE NO.

*529*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

*Rendley*

Note. This permit covers work outside of building only. Any work in  
walls of building is subject to Massillon Board of Health Regulations.